Archaeological Survey
Ballintober Castle
Ballintober, Co. Roscommon
Ireland


RO027-048002-

Niall Brady

for

Castle Studies Trust 2014 Grant award

Figures 1-17








Figure 1: Plan of Ballintober Castle

Source: O'Conor Don, 1899









Figure 4: Ortho image showing aerial view of present-day landscape

Source: Ortho image courtesy of Roscommon County Council






Figure 6: Comparative ground plans of keepless castles in Connacht and at Caernarvon

Sources:

Murphy and O'Conor 2008;

O'Conor Don 1899;

Sweetman 1985/86; <en.wikipedia.org/>




Figure 7: Detail from John Browne's Map of Connacht, 1591

Sources: Taken from Andrews 2003, original map TCD MS 1209/68




Figure 8: Nineteenth-century map details of Ballintober

Top: John Johnston 1812, in Pakenham Mahon collection, NLI

Bottom: OS 6-inch/mile, 1838




Figure 9: Detail from OS 25 inch/mile showing castle layout recorded in early 1900s

Source:

<a href="http://webgis.archaeology.ie/">http://webgis.archaeology.ie/</a>

Note:

NTS



Figure 10: Ballintober Castle, as drawn by Angelo Bigari in 1779.

The view looks west at the east wall from outside the castle


Source: NLI PD Coo 2122 TX-3-23



Top: View of Southwest corner tower by Wakeman.

The image is undated but is published by O'Conor Don' in 1899. Note the shattered nature of the base batter on the tower, and the absence of ivy and the visible extent of the stairwell, and the absence of any clear indication of the internal support column that now exists on the north end wall of the tower.

The fosse is filled with water, and the causeway across it is exaggerated.



Bottom: View of Southwest corner tower by unknown photographer, published by Fitzpatrick in 1935. Note the base batter has been repaired. The ivy growth that now covers much of the stonework is already established but it is possible to make out details on the residential block, while the fabric of the west perimeter wall north of the tower is exposed.

Figure 11: Ballintober Caste, historic images

Sources: O'Conor Don 1899 Fitzpatrick 1935




Figure 12: Gradiometry and Resistance Surveys, Ballintober Castle 2008

Target Archaeological Geophysics report, licence 08R262




Figure 13: Ground Penetrating Radar Survey, Ballintober Castle, 2009

Target Archaeological Geophysics report, licence 09R032






Figure 15: Ortho-images of Castle's west wall, exterior and interior view

wi - window/loop opening



